

Figure 1




Figure 2





Figure 3



AC in
Slow Solenoid
Fast Solenoid
Motor Start Relay

Pump Handle
Authorize
Pulser 1
Pulser 2
Ethernet - RS485

Figure 3a




Figure 4a




Figure 4b




Figure 4c




Figure 5




Figure 6




Figure 7

20




Figure 8